

Code couleur des résistances

6 - bandes



Couleurs
Noir
Marron
Rouge
Orange
Jaune
Vert
Bleu
Violet
Gris
Blanc
Or
Argent

Bande 1	Bande 2	Bande 3
0	0	0
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9

Multiplicateur
1 Ω
10 Ω
100 Ω
1 k Ω
10 k Ω
100 k Ω
1 M Ω

Tolérance
$\pm 1\%$
$\pm 2\%$
$\pm 0.5\%$
$\pm 0.25\%$
$\pm 0.1\%$

Cœf température
250
100
50
15
25
20
10
5
1

0.1 Ω
0.01 Ω

$\pm 5\%$
$\pm 10\%$

En
ppm/k